

2007-Test Beam Facility Running Log

Experiment Name	Date
Performance Testing of Strip-line Beam Position Monitor	2007.7.17-----7.20
Performance Testing of Parallel Plane Ionization Chamber	2007.7.18-----7.20
Seeds Radiation	2007.7.22-----
Background Testing of EMC and Luminosity Detector	2007.7.23-----

Updated by Peng Chen on July 23, 2007.

Some Photos:




Fig.1 BPM at E1 line



Fig.2 Parallel Plane Ionization Chamber at the end of E2 line




Fig3. Typical pickup signals of BPM02 at the end of 40m coaxial cables




Fig.4 Typical signals of anode and No.6 strip